PSU Controller

+5V PCM	5V Relay
aGND	aGND
M+	M-
+5V DAC	Relay1
+5V DAC	Relay2
+5V DAC	Relay3
dGND	Relay4
dGND	DIRECT
dGND	-12V
dGND	+12V

Sterowanie masa

Relay1=RCA1
Relay2=RCA2
Relay3=PCM2704
Relay4=DAC,Malina
DIRECT=Tone/ctrl

M+ Volume motor
M- Volume motor



+5V DAC	+5V DAC	+12V	-12V	NC	SPDIF_IN	IN_L	IN_R
+5V DAC	+5V DAC	dGND	dGND	dGND	dGND	aGND	aGND

DAC

+12V	DIRECT	M-	M+	+5V	OUT_R	OUT_L	aGND
-12V	dGND	dGND	dGND	dGND	aGND	aGND	aGND

PREAMP